



Fig.5 Event tree diagram for the inducer blade fatigue fracture caused by vibration